

**Technische Information**

*Technical Information*

**15/2018**

**911 GT3 Cup (991) Gen.II**

**ENTFALL HALTER KRÜMMER**

*REMOVAL MANIFOLD BRACKET*

**Fahrzeug / Vehicle:**

**911 GT3 Cup (991) Gen.II**

**Bauteil / Part:**

**Halter Krümmer / Exhaust Manifold Bracket**


**Modell / Model**

**ab 2017 / from 2017**

Porsche Motorsport weist darauf hin, dass der Halter des Krümmers (7), die dazugehörigen Schrauben (8) und das Spannband (9) ab sofort nicht mehr zur Befestigung des Krümmers am Motor nötig sind. Diese Bauteile sind für die Teilnahme an den Porsche Markenpokalen zu entfernen. Neue Motoren werden aus produktionstechnischen Gründen weiterhin mit Halter ausgeliefert. Auch bei neuen Motoren sind die genannten Bauteile zu entfernen.

Entfallende Bauteile:

- **9A11115479C / 9A11115489C** HALTER KRUEMMER
- **90038500102** 6RD-SHR BM 8X20
- **9A11131319A** Z SPANNBAND



Porsche Motorsport informs that the bracket (7) for the exhaust manifold, the corresponding bolts (8) and the clamp (9) are now no longer required to fasten the exhaust manifold to the engine. These components must be removed when participating in Porsche One Make Cup events. Due to manufacturing reasons, new engines will continue to be supplied with the bracket. The mentioned parts should also be removed from new engines.

Parts to be removed:

- **9A11115479C / 9A11115489C** EXHAUST MANIFOLD BRACKET
- **90038500102** TORX SCREW BM 8X20
- **9A11131319A** CLAMP

